DATE: 13 May 1947 | HOUR: 1045 | LOCATION: Over water, 3 mi. SW of Pt. Loma | PURPOSE: Glide Bombing | SERIAL NO: 3-47

PILOT'S NAME, RANK & SERVICE | BRANCH & UNIT TO WHICH PILOT ATTACHED | CODE
WALDMAN, A. C. Jr., Lt., USN | VF-11-A

UNIT TO WHICH AIRCRAFT ASSIGNED | OPERATING FROM | CHAIN OF COMMAND
VF-11-A | NAS-San Diego, Calif. | CAG-11, CFWC ComAirPac

PILOT'S NUMBER RATING	TOTAL HRS.	TOTAL HRS. LAST 6 MONTHS	TOTAL HRS. LAST 3 MONTHS	HRS. THIS MODEL	TIME IN FLIGHT
	819.2	86.8	85.9	79.3	25 mins.

CEILING	VISIBILITY	WIND	FORCE	DARKNESS	NIGHT HRS. LAST 6 MOS.	NIGHT HRS. LAST 3 MOS.
Unl.	4		3-5	No		

WEATHER AT TIME OF ACCIDENT	INSTRUMENT HRS. LAST 6 MONTHS	INSTRUMENT HRS. LAST 3 MONTHS	TYPE OF CLEARANCE
X CONTACT INSTRUMENT			Contact

MANEUVER & ALT. OF MANEUVER | ANGLE OF IMPACT, STOPPING DIST. & EST. SPEED
Water Landing | Full stall Unk. 70 K

PREVIOUS ACCIDENT RECORD

INJURIES TO PILOT | D | INJ

NONE

NAME & RANK OF OTHER PERSONNEL

AIRCRAFT MODEL & NO. | WAS EJECTION USED
F8F-1 #94928 | X YES | NO

DAMAGE: A B C D E | DAMAGE DESCRIPTION & REMARKS
AIRCRAFT X | Total loss of aircraft and engine
ENGINES
GEN. NATURE X
SPECIFIC TYPE OF ACC.
CAUSE ANALYSIS
CLASSIFICATION OF ACCIDENT AND REASONS

SPECIFIC ERRORS:

No determined due to loss of aircraft.

ANALYSIS:

On 13 May 1947 at 1015, Lt. A.C. WALDMAN pilot of F8F-1 BuNo. 94928 lead a division of four planes on a glide bombing hop. The target was a radio controlled boat located about 3 mi. SE of Point Loma. After arriving on station the target was not ready so the flight circled for about 25 mins. After making the first dive of about 40° and pull out the pilot noted something wrong. His first impression was that he had grayed out. When he realized this was not the case he knew the engine had stopped. A complete examination of the cockpit followed with all readings normal except cylinder head temperature 140°c and manifold pressure approx. 32", regardless of throttle position. No reading was noted in the full closed position. The emergency fuel pump was turned on prior to the dive and, the mixture control was advanced to full rich. Fuel pressure was 21 lbs. psi. The pilot was at 3000 with 90 knots air speed and decided to make a 180° turn and land beside the target control boat. This decision was made and maintained despite necessity for a down wind landing. The sea was calm and wind force about 3 to 5 knots. Flaps were lowered at about 800

(over)

TALLY

AIRCRAFT ACCIDENT CARD
FORM NAVAER 339 C (REV. 9-45)

D	R	A-B	OTHER
	X		

GENERAL CAUSES OF ACCIDENT | SPECIFIC CAUSES OF ACCIDENT | MATERIAL | OTHER | PRIMARY-BOTTOM ROW | SECONDARY-TOP ROW | SPECIFIC TYPE OF ACCIDENT | GENERAL NATURE OF ACCIDENT | AIRCRAFT CLASS | ORGANIZATION